

## “360 Walk-Around Program Reference Sheet”

### 360 Reminders and their Use:

- 1) The 360 magnet is generally placed on the opposite side of the operator cab entry door, in the rear, in a safe, easily accessible area while the equipment is not in operation (while the operator is outside of the cab)
- 2) Cones may be used as a substitute for the magnet if the equipment or conditions make it challenging for the magnet to work.
- 3) Before entering the cab of the machine, the operator shall perform a 360 walk around while conducting a good visual inspection around the exterior of the equipment and the surroundings to identify hazards.

### Mobile Equipment Best Practice:

1. After the operator has exited the equipment (while the equipment is not in operation), the operator is required to place the 360 walk around reminder on the side of the machine opposite of the cab door in a safe, easily accessible area. (See yellow boxes in pictures below for reference)
2. Prior to operating the equipment, the operator is required to perform a 360-degree walk around the equipment. At this time, the operator shall remove the 360 walk around reminder and can proceed with operating the equipment. The operator shall not operate the equipment without completing a 360-degree walk around observation and removing the 360 magnet or other reminder still in place.



### Specialized Equipment Not Addressed:

If equipment is used on Cajun jobsites that does not have a recommended location for the 360 walk around reminder, site management shall determine the best/safest location.

## DOCUMENT ACKNOWLEDGEMENT FORM

Document Name: (please print neatly)	
Date: (please print neatly)	<i>By signing, I acknowledge the information in this document and agree to work in accordance with it</i>
	<input type="checkbox"/> New Training <input type="checkbox"/> Refresher Training

	PRINT NAME	SIGNATURE	JOB #	EMPLOYEE # or SS#
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				